CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorised person is prohibited by law.

		slovakia				REPORT					
ECT	Krizi	, Nationa	l Enterpri	se, Prague-	Smichov .	DATÈ DISTR			3 March		X1
					V.	NO. OF PA	GES	14			
E OF I	NFO.				·	REQUIREME	NT NO.	RD			2
CE ACC	QUIRED					REFERENCES	5				
			This is l	JNEVALUAT	TED Inform	mation					
			THE SOURCE EV	ALUATIONS IN TH PRAISAL OF CONT (FOR KEY SEE I	ENT IS TENTA	E DEFINITIVE. TIVE.		***************************************			
1.	7	at the e	withwest co	, is locate	a crossrc	SACS OF PI	zenska	AVOILUE	s and	™ 25X	(1
2.	There a one won	a Street, re always ks guard ks. At n	Prague-Smi die or two gates at the gates ight there	chov. The cekeepers (v . Iwo memb are two members	works gus bers of t ers of th	ard) at the the works (ne works gr	e main guard (entra:	nce and	rol ers'	
	There a one won the won post, a	a Street, re always ks guard ks. At n nd 2 mili	Prague-Smi	chov. The	works gus bers of there of the contract of the	ard) at the the works one works go	e main guard (uard i	entra constant the	nce and ntly patr gatekeepe	nd	
	There is when re	a Street, re always ks guard ks. At n nd 2 mill s no spec pairs hav	Prague-Smi	chov. The second of the second	works gus bers of there of the contract of the	ard) at the the works one works go	e main guard (uard i	entra constant the	nce and ntly patr gatekeepe	nd	
	There is one work the work one work the work of the plup remain. Personn The plup rison great works for 10	a Street, re always ks guard ks. At n nd 2 mili s no spec pairs hav el nt has ab ors or bri issatisfs anteen. minutes b Party	Prague-Smi die grup gate at the gate ight there tismes: pat ial guard : a to be mad out 820 em gade worke ction with The food i The food i	chov. The second of the second	works gua- bers of the ers of the th a dog. et depart of the v whom ab- in the pl The maj- litical: etings fully meet.	ard) at the the works go the works guardout 80 are lant. Mor ority of works from the entings. The	e main guard (uard in is all d accord women cale is corkers or is all	entrai constant the participants of the apanies	nce and ntly patr gatekeeps ocked, ar s the rep re are no There : ed in the ery day e held of	nd pair- o is e	25
3. 4.	There is one work the work the work the work the work the plus the plus the plus the prison to the plus the plu	a Street, re always ks guard ks. At n nd 2 mili s no spec pairs hav el nt has ab ors or bri dissatisfs anteen. minutes b overy week	Prague-Smi die grup gat at the gate ight there tismes: pat ial guard : a to be mad out 820 em gade worke ction with The food i efore each members ha	chov. The ckeepers (v. Iwo member are tho member crolling within the secrete a member ployees, of rs working salaries. s good. Poshift. Me ve fortnigh	works gua- bers of the sers of the a dog. at depart of the version of the major of the well or version of the version o	ard) at the the works go the works guardout 80 are lant. Mor ority of works from the entings. The	e main guard (uard in is all d accord women cale is corkers or is all	entrai constant the participants of the apanies	nce and ntly patr gatekeeps ocked, ar s the rep re are no There : ed in the ery day e held of	nd pair- o is e	25
3. 4.	There is one work the work the works for 10 a mont meets	re always ks guard ks. At n nd 2 mili s no spec pairs hav el nt has ab ers or bri dissatisfs canteen. minutes b h. Party every week nt's mans	Prague-Smi die or two gate at the gate ight there tiament, part ial guard : a to be made out 820 em gade worker ction with The food i efore each members ha their m	chov. The cekeepers (v. Iwo member are tho member crolling with in the secrete a member ployees, of rs working salaries. s good. Poshift. Me ve fortnigh eetings are	works gua- bers of the ers of the th a dog. at depart of the v whom ab- in the p. The maj- litical: etings for tly meet: well or	ard) at the the works go the works guardout 80 are lant. Mor ority of works from the entings. The	e main guard (uard in is all d accord women cale is corkers or is all	entrai constant the participants of the apanies	nce and ntly patr gatekeeps ocked, ar s the rep re are no There : ed in the ery day e held of	nd pair- o is e	25
3. 4.	There is one work the work post, if there is when reman. Person The pluprison great works for 10 a mont meets The pluprison control of the plupr	a Street, re always ks guard ks. At n nd 2 mill' s no spec pairs hav el nt has ab rs or bri issatisfs santeen. minutes t h. Party every week ant's mans department	Prague-Smi die or two gate at the gate ight there tiament, part ial guard : a to be made out 820 em gade worker ction with The food i efore each members ha their m	chov. The cheepers (we meanly are the member of the cheepers) of the cheepers of the cheepers, of the cheepe	works gua- bers of the ers of the th a dog. at depart of the v whom ab- in the p. The maj- litical: etings for tly meet: well or	ard) at the the works go the works guardout 80 are lant. Mor ority of works from the entings. The	e main guard (uard in is all d accord women cale is corkers or is all	entrai constant the participants of the apanies	nce and ntly patr gatekeeps ocked, ar s the rep re are no There : ed in the ery day e held of	nd pair- o is e	25

(NOTE: Warkington distribution indicated by "X"; Field distribution by "#".)

- 2 -

25X1

```
25X1
    Chairman of the works council is Jaroslav Riha
    There are always to Russian engineers (m) in the factory who are constantly writing
10.
     and drawing in the office.
                                                                                         25X1
    Production
    Plates and bars used in production are supplied by the Poldina Foundry in Kladno
     (N50-09, El4-06). Electricity is supplied by the Tatra plant main transformers.
                                                                                         25X1
12. Production (daily) (sic): 30 electric meters
                              70 thermal relays
                             130 time limit relays
                             100 small transformers (from 220 to 24 volts)
                              12 transformers for 2400 v, monthly (sic)
13. Defects in production are due to a shortage of nonferrous metals. The largest
     percentage of defective production is of time-fluit relays, about 45%.
14. Destination of finished products:
     a. USSR: Fime-limit relays, large transformers;
     b. Bulgaria and Hungary: Time: Minist and thermal relays;
     c. Czechoslovakia Blectric meters, mainly for the communal concern in Prague.
15. The Five-Year Plan is being fulfilled 105%.
    Machinery
    In the basement:
16.
     Workshop - 22 eccentric presses, Wolman make;
                 1 large friction press, Csech;
                 1 metal shears, TOS, new, outting up to a thickness of 3 mm.
     Workshop - 1 new, electromagnetic Swiss grinding machine.
      No. 5
     Workshop - 2 compressors (one 24 HP and 82 HP).
      No. 16
     First floor:
     Workshop - 10 spot welding machines, some of which are for seaming -
                old, Czech and Swiss;
      No. 7
                3 vertical drilling machines, Wolman, old;
                1 horisontal drilling machine; Wolman, old;
                3 old vertical milling machines.
     Maintenance shop (#10): 3 vertical drilling machines of the older Csech type;
                              1 metal shears, TOS, new;
                               3 new lathes TOS, turning length 1000 mm. (SVR 18);
                               3 new milling machines, TOS;
                               1 large and 1 small vertical milling machines.
     Forge: (約2): 1 old vertical drilling machine,
                    2 new small power hammers, TOS.
     Joinery shop: (#13): 3 belt saws for wood.
     Pressing shop (#15): 1 winding machine for making tubes, large, eld.
                                   3 old vertical drilling machines,
     Maintenance workshop (#16)
                                   1 generator with a 12 HP engine.
     for electrical
     equipment:
```

- 3 -

25X1

Second floor:

Automatic machine shop (#15): 50 automatic machines (of which 6 are Russian Type ZIM, new);

2 centrifugal machines for cleaning oil off products (rough);

2 new lathes, TOS;

12 small bench presses for fine work, new;

10 small bench drilling machines for holes smaller than 1 mm;

2 watchmaker's lathes, Swiss (1937).

Grinding shop (#12): 2 special precis ion automatic grinding machines for flat grinding (with indicators) year 1952.

Grinding shop for drills (#14): 3 grinding machines, older type, Csech.

Tool shop (#9): 8 new TOS lathes, turning length 1800 mm; 2 new universal milling machines, TOS, new; 1 new plate shears.

Third floor:

Tool shop (#6: 7 old lathes, turning length 1000 mm, Wolman; 2 milling machines (horizontal); 1 vertical milling machine, new; 1 old plate shears.

Painting shop (#7): 12 electric drying ovens; 7 paint sprays.

Workshop (##) 12 4 large centrifugal machines for complete cleaning of finished products.

Assembly shop (#13): 7 old, drilling machines, Wolman (for electric relays); 3 old winding machines, Swiss.

Production room for preparatory work for relays (#13):

h new drills with pivot arms; 1 large new lathe, Wolman, turning length 1800 mm; 4 old lathes, Wolman, turning length 1000 mm; 2 old, horisontal, universal milling machines.

Galvanizing shop (#14): 3 large emery wheels;
2 large, new bench grinders, Czech;
8 galvanizing baths.

Fourth floor:

Apprentices' workshop (#6): 5 new lathes, TOS, turning length 1000 mm; 4 old vertical drilling machines; 2 old milling machines;

Assembly shop for transformers (#7): 4 old pillar drills; 12 old coil-winding machines, Swiss.

Painting shop for coils (#9): 4 electric ovens for drying coils.


Fifth Moor:

Assembly shop for transformers: 4 vertical drilling machines, old, Wolman; 10 old coil-winding machines, Swiss.

Workshop for preparing parts for transformers (#8):

4 old vertical drilling machines; 4 small presses for pressing plates for transformers; 1 old press (where plates for transformers are pressed and screwed).

Secret department (#9): 2 new vertical drilling machines; 1 new radial drilling machine; 9 new coil-winding machines, Swiss.




- 5 -

25X1

Krizik, NATIONAL ENTERPRISE (Basement)

Scale 1:500




SECRET/U.S. OFFICIALS ONLY


Approved For Release 2008/06/19: CIA-RDP80-00810A005800320001-5 SECRET/U.S. OFFICIALS ONLY 25X1 - 6 -1 st Floor Scale /:500 11 10 12 M रग रग /3 20 47 1/4 17 15 25

SWORRT/U.S. OF TOTALS


- 7 -

25X1





SECRET/U.S. OFFICIALS ONLY




SECRET/U.S. OFFICIALS ONLY



- 10 -

25X1



- 11 -

Key to the plan of the basement

- ı. Yard
- 2. Corridor
- 3. Lifts
- 4. Main electricity distributor, lead with cables from the town network, 500-wolt tension. Main meters for the building.
- 5. Workshop where large dies for presses are ground on a grinding machine with magnetic chunk
- 6. Pressing shop where plates are pressed for the transformers and contacts for electric meters, and menferrous metal relays.
- 7. Larder for works kitchen
- 8. Store for iron material
- 9. Boiler room with finalities. Fully automatic.
- 10. Store for glass tops for electric meters
- 11. Distributing room for dies for presses
- 12. Presses
- 13. Plate shears
- 14. Electromagnetic grinder
- 15. Stairs
- 16. Compressor room
- 17. Compressors

Key to plan of first (ground) floor

- 1. Gate-keepers' post
- 2. Canteen
- 3. Corridors and staircase
- 4. Dining room
- 5. Kitchen
- 6. Cloakroom
- 7. Spot-welding shop where metal cases for electric meters and electric relays are drilled and welded.
- 8. Office of the foremen of the spot-welding shop
- 9. Despatching department
- 10. Maintenance workshop for precision tools
- Office of foremen of the maintenance workshop 11.
- 12. Forge used for maintenance
- 13. Joinery shop crates and furniture for the factory are made here.
- 14. Lift
- 15. Pressing shop for paper tubes for coils16. Workshop for electrical maintenance
- 17. Offices for stores and expenses
- 18. Hardening shop for all implements and compounds for electric meters and transformers.
- Works power station with one alternating current generator driven by a 19. 24-cylinder diesel engine. Used in emergency and at maximum cutput can supply factory's needs for two hours.
- 20. Stores of factory militia
- 21. Yard 22. Goods lift
- 23. Generator for producing current for battery loading
- 24. Vertical drilling machines
- 25. Press for production of paper tubes
- 26. Pillar drilling machine 27. Belt saws for wood
- 28. Power hammers 29.

La account to a sale of

- 35. Utiling machine for drilling large dismeters
 36. Milling machines
- 37. Vertical drilling machines
- 38. Seaming machines

SECIAL TOUS. OFFICIALS CHLY

- 12 -

- 39. Electric generators
- 40. Hardening ovens
- 41. Small hardening ovens

Key to the plan of the second floor

- Gonds lifts
- 2. Corridors with stairs
- 3. Balcomy
- 4. Yard
- 5. Offices
- Stores for electrotechnical regainments
- Cloamroom
- 8. Lavatories and washroom
- 9. Tool shop makes dies for the pressing shop
- 10. Tools distribution
- Sorting room for products from automatichmechines 11.
- 12. Grinding shop where fine dies are ground flat
- 13. Offices of tool shop foremen
- 14. Grinding shop for drills
- 15. Automatic machines shop makes screens, split-pine, rivete, pine, axlee, and wheels
- 16. Offices for foremen of the automatic mechines shop
- 17. Works doctor's office
- 18. Automatic lathes for screw production and so on
- 19. Centrifugal machines (for cleaning oil off automatic lathe products)
 20. Precision tools (small presses, drille, for working on small articles)
- 21. Lathes
- 22. Special grinders for grinding drills
- 23. Swiss grinders for grinding dies
- 24. Lathes
- 25. Belt saws for metal
- 26. Milling machines

-Key to the plan of the third floor

- 1. Goods lift
- 2. Corridors with stairs
- 3. A Tracky
- Yard
- 5. Technical offices
- 6. Tools shop does the rough work on dies for presses
- Painting shop where all products are painted or varnished
- 8. Centrifugal machines for cleaning products from automaticulathos (final cleaning)
- Testing shop where thermal and time-limit relays and transformers are tested (including large volumes)
- 10. Control room for relays11. Foreman of relays assembling shop12. Assembling shop for relays
- 13. Production room: preparations for relays
- 14. Galvanizing shop
- 15. Grinders 16. Galvanising baths
- 17. Lathes
- 18. Milling machines
- 19. Drilling machines with revolving top 20. Vertical drilling machines
- 21. Coil-winding machines
- 22. Centrifugal machines
- 23. Drying ovens in painting shop
- 24. Lathes 25. Milling machines
- 26. Plate shears

Key to the plan of the fourth floor

- 1. Goods lift
- 2. Corridors and stairs
- 3. Balcomy
- 4. Yard
- Offices
- 6. Apprentice's workshop

- 13 -

- 7. Assembling shop for transformers where transformers, mostly 220 to 2h volts, are made, chiefly for the USSR.
- Gauging shop where electric meters are adjusted and plugged
- 9. Painting shop for coils. Coils for electric meters are painted with insulating varnish.

- 10. Assembling and cloakrooms
 11. Lavatories and cloakrooms
 12. Vertical drilling machines
- 13. Coil-winding machines
- 14. Drying ovens for coils
- 15. Vertical drilling machines
 16. Coil-winding machines
- 17. Lathes
- 18. Drilling machines
- 19. Milling machines
- 20. Office of foreman for the electric-meter assembling shop

Key to the plan of the fifth floor

- 1. Goods lift
- 2. Balcomy
- Yard
- 4. Assembling shop for transformers where the final processing of transformers is carried out
- 5. Packing shop for electric meters
- 6. Office of foremen of transformer assembly shop
 7. Office of foremen of transformers workshop

- 8. Workshops for preparation of parts for transformers
 9. Secret department (production of parts for the aircraft industry probably measuring instruments for jet aircraft)
- 10. Coil-winding mach: 11. Drilling machines Coil-winding machines
- 12. Presses, eccentric, production of plates for transformers
 13. Coil-winding machines
- 14. Drilling machines 15. Flat roof,

